







0499 / RC0499






v012
10.10.2022
A. H.
[cm]



vinci
play








[cm]











vinci
play



[cm]



vinci
play




[cm]




2h



vinci
play



044114
x1



044115
x1



147_130_90
x2



147_159_90
x3

Q1



149_130_90
x2



149_159_90
x3




045192
x1

K1



042118
x4

K2









042166
x4

K3




042167
x4

4x	WD1
34x	8x50 sxi
1x	E202
6x	i29
1x	V001






Q1






8x50sxi

Ø5.5






6x50sxi

Ø4,5





7x35sxi

Ø5.5




5x40sxi

Ø3,5






[cm]

vinci
play




8x50 sxi

i29



V001





WD1



[cm]




vinci
play





8x50 sxi




48h



E202



8x50 sxi



[cm]



vinci
play