






WD1485



v012
11.01.2022
A. D.
[cm]





vinci
play








[cm]



vinci
play




	K2, K3
M10x120 x8	
NOT INCLUDED	




[cm]

 x2			 x2 0,06 m ³	 48h
--	---	---	---	---


vinci
play




14706290
x2



K1
142102
x2




K2
142108
x2



K3
142100
x2











141282
x9



096104
x2

4x	6x80 sxt
18x	7x35 sxi
8x	8x50 sxi
2x	WD1
1x	V002







6x80 sxt

8x50 sxi




[cm]


vinci play



[cm]



vinci
play



Part No:
000000-
00000

000000-00000

